



DNV Id. No.:

Ref:- BDA/2011/297B

Date:- 2011/12/28

## DET NORSKE VERITAS

TO,  
M/s. Sealexcel (India) Pvt. Ltd.  
Plot No. 300/1&2, At Post-Mahi,  
Via Chhapi, Pirojpur-Mahi Road,  
Taluka - Vadgam, Dist. Banaskantha,  
Gujarat, INDIA, PIN 385210

With reference to your enquiry requesting us to witness the helium leak test for instrumentation tube fitting assembly of 1/4" ODT, 3/8" ODT, 1/2" ODT, 3/4" ODT and 1" ODT, our undersigned surveyor visited your works on 28<sup>th</sup> December 2011 and witnessed the same on the tube fitting assembly pre-selected by you.

### TEST REPORT

Type : Sealexcel "Well-lok" twin ferrule tube fitting  
Size : 1/4" ODT, 3/8" ODT, 1/2" ODT, 3/4" ODT and 1" ODT  
Assly serial No. : HLT-250/WL01, 02 & 03 for 1/4" ODT,  
HLT-375/WL01, 02 & 03 for 3/8" ODT  
HLT-500/WL01, 02 & 03 for 1/2" ODT  
HLT-750/WL01, 02 & 03 for 3/4" ODT  
HLT-1000/WL01, 02 & 03 for 1" ODT  
Procedure No.. : PR-HLDT-WL/01 Dated 15.07.2011  
Drg. : TA-002HLT/Rev 01 Dated 18.03.2011

Test result for witnessed helium leak testing in accordance to manufacturer defined procedure number PR-HLDT-WL/01 dated 15.07.2011 and tube fitting assembly drawing number TA-002HLT/Rev 01 dated 18.03.2011 found satisfactory. For further details please refer manufacturer inspection report number HLDT-TR-01 dated 28.12.2011

  
Manoj Kumar Ranchal  
Surveyor of DET NORSKE VERITAS AS

If any person suffers loss or damage which is proved to have been caused by any negligent act or omission of Det Norske Veritas, then Det Norske Veritas shall pay compensation to such person for his proved direct loss or damage. However, the compensation shall not exceed an amount equal to ten times the fee charged for the service in question, provided that the maximum compensation shall never exceed USD 2 million. In this provision "Det Norske Veritas" shall mean the Foundation Det Norske Veritas as well as all its subsidiaries, directors, officers, employees, agents and any other acting on behalf of Det Norske Veritas.